



04/12/2021

Grand Rapids Rail Yard
Flint, Lansing, Grand Rapids, MI

2037-OH #9

| Procedure | Sieve/Test | Average | Unit |
|-----------|-----------------------|---------|------|
| | 3/4" (19mm) | 100.0 | % |
| | 1/2" (12.5mm) | 100.0 | % |
| | 3/8" (9.5mm) | 100.0 | % |
| | #4 (4.75mm) | 87.4 | % |
| | #8 (2.36mm) | 24.6 | % |
| | #16 (1.18mm) | 8.9 | % |
| | #30 (.6mm) | 4.9 | % |
| | #50 (.3mm) | 4.0 | % |
| | #100 (.15mm) | 3.4 | % |
| | #200 (75µm) | 2.65 | % |
| | FM | 4.67 | |
| | Wash Loss (#200/75um) | 2.4 | % |
| | Total Moisture | 3.4 | % |

Name/Title

Dan Ferris / QC