



Ottawa Lake
Pit # 58-003
7555 Whiteford Rd
Ottawa Lake, MI 49267

07/12/2019

2126-MDOT 6AA Wayne County Limestone

Procedure	Sieve/Test	Average	Unit	MDOT 6AA Wayne County
	1 1/2" (37.5mm)	100.0	%	100-100
	1" (25mm)	100.0	%	95-100
	3/4" (19mm)	82.2	%	
	1/2" (12.5mm)	41.7	%	30-60
	3/8" (9.5mm)	21.4	%	
	#4 (4.75mm)	3.9	%	0-8
	#8 (2.36mm)	1.5	%	
	Wash Loss (#200/75um)	0.7	%	0-2