



04/12/2021

Patterson
 ASI # 03-93
 3700 Patterson Rd.
 Middleville, MI 49333

2223-MI 23A Gravel

Procedure	Sieve/Test	Average	Unit	MI 23A Gravel Spec
	1" (25mm)	100.0	%	≥100
	3/4" (19mm)	95.4	%	
	1/2" (12.5mm)	85.2	%	
	3/8" (9.5mm)	78.7	%	60-85
	#4 (4.75mm)	63.9	%	
	#8 (2.36mm)	52.4	%	25-60
	#16 (1.18mm)	44.8	%	
	#30 (.6mm)	38.0	%	
	#50 (.3mm)	25.3	%	
	#100 (.15mm)	13.5	%	
	#200 (75µm)	10.14	%	
	Fractured Faces (>1)	60.9	%	25.0-100.0
	-#200 (75um)	10.2	%	
	Wash Loss (#200/75um)	9.8	%	9.0-16.0
	Total Moisture	4.97	%	

Name/Title

Dan Ferris / QC