



04/12/2021

Patterson
 ASI # 03-93
 3700 Patterson Rd.
 Middleville, MI 49333

2234-MDOT 34R Gravel

Procedure	Sieve/Test	Average	Unit	34R Spec
	1/2" (12.5mm)	100.0	%	
	3/8" (9.5mm)	99.2	%	90-100
	#4 (4.75mm)	28.4	%	
	#8 (2.36mm)	4.0	%	0-5
	#16 (1.18mm)	2.1	%	
	#30 (.6mm)	1.3	%	
	#50 (.3mm)	0.9	%	
	#100 (.15mm)	0.8	%	
	#200 (75µm)	0.74	%	
	Wash Loss (#200/75um)	0.7	%	0.0-3.0
	Total Moisture	2.41	%	

Name/Title

Dan Ferris / QC