



Patterson
ASI # 03-93
3700 Patterson Rd.
Middleville, MI 49333

07/07/2020

2234-MDOT 34R Gravel

Procedure	Sieve/Test	Average	Unit	34R Spec
	1/2" (12.5mm)	100.0	%	
	3/8" (9.5mm)	99.1	%	90-100
	#4 (4.75mm)	15.4	%	
	#8 (2.36mm)	3.4	%	0-5
	#16 (1.18mm)	1.3	%	
	#30 (.6mm)	0.8	%	
	#50 (.3mm)	0.7	%	
	#100 (.15mm)	0.6	%	
	#200 (75µm)	0.46	%	
	Total Moisture	2.22	%	